


AR4 Upgrade Guide for Increasing Torque in Joint #3

This guide reuses the older Nema 23 gearbox (SKU: 23HS22-2804D-HG50-AR4), initially used in joint #2 in manual version 1.5; however, you have the flexibility to choose a motor that suits your preference.



Created for the AR4 community by Elijah Peralta
Founder of Assista Robotics
Elijahperaltav@gmail.com
[Twitter.com/Assistabotics](https://twitter.com/Assistabotics)

This guide is not endorsed by Annin Robotics

Electrical Safety

- ▶ **ELECTRIC SHOCK HAZARD.** The construction of this control enclosure poses potential exposure to alternating current and direct current which has the potential to cause injury or death. This equipment should be constructed and serviced by trained or qualified persons.
- ▶ Keep the area around the device clear and free from dust before, during, and after installation.
- ▶ Wear safety glasses if you are working under any conditions that could be hazardous to your eyes.
- ▶ Do not perform any actions that create a potential hazard to people or make the equipment unsafe.
- ▶ Never install or manipulate wiring during electrical storms.
- ▶ Never install electrical jacks in wet locations unless the jacks are specifically designed for wet environments.
- ▶ Operate the device only when it is properly grounded.
- ▶ Ensure that the separate protective earthing terminal provided on this device is permanently connected to earth.
- ▶ Replace fuses only with fuses of the same type and rating.
- ▶ Do not open or remove chassis covers or sheet-metal parts unless instructions are provided in the hardware documentation for this device. Such an action could cause severe electrical shock.
- ▶ Do not push or force any objects through any opening in the chassis frame. Such an action could result in electrical shock or fire.
- ▶ Avoid spilling liquid onto the chassis or onto any device component. Such an action could cause electrical shock or damage the device.
- ▶ Avoid touching uninsulated electrical wires or terminals that have not been disconnected from their power source. Such an action could cause electrical shock.
- ▶ Always ensure that all modules, power supplies, and cover panels are fully inserted and that the installation screws are fully tightened.

Bill of Materials

It is recommended to make or source these parts out of aluminum, however they can be 3d printed as well:

☐ Key for J3 Motor Shaft

☐ L10 Pulley (J3 long pulley), 14mm inner bore diameter *

3D print these parts:




☐ J3 Front Spacer

☐ J3 Side Spacer (2)

☐ J3 motor bracket

☐ Key for J3 motor shaft (to fabricate the aluminum one)

☐ Tool for alignment (2)



Optional helpful tools:

☐ V-drill guides, Metric or ANSI

* It is highly recommended to reuse the J3 pulley on the old J3 motor or source a new one from Annin Robotics (info@anninrobotics.com)

You will need to extend the pulley's inner shaft diameter to 14mm

Visit the uxcell Store

uxcell M4x90mm Fully Thread Hex Socket Head Knurle Cap Screw Bolt Black 5pcs

4.2



Size: **M4x90mm**



Click image to open expanded view

CL-34-SS Carr Lane Manufacturing Shoulder Screw: Diameter 5/8, Length 5/8

Brand: Carr Lane Manufacturing
Search this page

\$8⁵⁶


| | |
|-----------------|---|
| Material | Alloy steel, heat treated Rc 32-43, black oxide finish. DFARS and RoHS compliant. |
| Metal Type | Stainless Steel |
| Brand | Carr Lane Manufacturing |
| Thread Coverage | Fully Threaded |
| Fastener Type | Machine Screw |

- About this item
- Shoulder Diameter: 5/8
 - A: 1/2-13
 - B: 5/8
 - D: 3/8
 - E: 3/4

Visit the ZOFORTY Store

2 Pack 6061 T6 Aluminum Sheet Metal 6 x 6 x 0.236 (1/4) Inch Flat Plain Plate Panel Aluminum Sheet Plate Finely Polished and Deburred, 6mm Thick

4.8



Delivery

Pickup

\$16⁹⁹ (\$8.50 / Count)

Required parts:

- ☐ M4 x 90 socket head screws (4)
- ☐ M4 x 8 set screw (1)
- ☐ M5x20 hex flat head screws (4)
- ☐ 6 x 6 x 0.236 aluminum sheet (1)
- ☐ HK1612 Needle Roller Bearing (1)
- ☐ CL-34-SS Shoulder Screw Diameter 5/8, Length 5/8 (1)

Required tools:

- ☐ Center punch
- ☐ 3.5 mm (9/64 0.1406) drill bit
- ☐ 11.11 mm (7/16 inch) drill bit
- ☐ 14mm (9/16 0.5511) drill bit
- ☐ <=5mm (3/16 0.1968) mill bit
- ☐ M4 tap
- ☐ M5 tap
- ☐ 12.7 mm - 13 TPI (1/2 inch - 13 TPI) UNC tap

Metric Alloy Steel Hex Drive Flat Head Screws

| Lg., mm | Threading | Min. Thread Lg., mm | Head Dia., mm | Head Ht., mm | Drive Size, mm | Tensile Strength, psi | Specifications Met | Pkg. Qty. | | Pkg. |
|--|----------------|---------------------|---------------|--------------|----------------|-----------------------|---------------------|-----------|-----------|-------|
| Black-Oxide Class 10.9 Alloy Steel—90° Countersink Angle | | | | | | | | | | |
| M4 × 0.7 mm | | | | | | | | | | |
| 14 | Fully Threaded | — | 8 | 2.3 | 2.5 | 120,000 | DIN 7991, ISO 10642 | 100 | 91294A193 | 12.50 |
| 16 | Fully Threaded | — | 8 | 2.3 | 2.5 | 120,000 | DIN 7991, ISO 10642 | 100 | 91294A194 | 7.57 |
| 18 | Fully Threaded | — | 8 | 2.3 | 2.5 | 120,000 | DIN 7991, ISO 10642 | 100 | 91294A195 | 12.89 |
| 20 | Fully Threaded | — | 8 | 2.3 | 2.5 | 120,000 | DIN 7991, ISO 10642 | 100 | 91294A196 | 8.93 |
| 22 | Fully Threaded | — | 8 | 2.3 | 2.5 | 120,000 | DIN 7991, ISO 10642 | 50 | 91294A197 | 13.52 |
| 25 | Fully Threaded | — | 8 | 2.3 | 2.5 | 120,000 | DIN 7991, ISO 10642 | 100 | 91294A198 | 10.91 |
| 30 | Fully Threaded | — | 8 | 2.3 | 2.5 | 120,000 | DIN 7991, ISO 10642 | 100 | 91294A200 | 17.91 |
| 35 | Fully Threaded | — | 8 | 2.3 | 2.5 | 120,000 | DIN 7991, ISO 10642 | 50 | 91294A202 | 11.59 |
| 40 | Fully Threaded | — | 8 | 2.3 | 2.5 | 120,000 | DIN 7991, ISO 10642 | 50 | 91294A204 | 12.85 |
| 45 | Fully Threaded | — | 8 | 2.3 | 2.5 | 120,000 | DIN 7991, ISO 10642 | 50 | 91294A484 | 16.75 |
| 50 | Fully Threaded | — | 8 | 2.3 | 2.5 | 120,000 | DIN 7991, ISO 10642 | 25 | 91294A537 | 15.58 |
| M5 × 0.8 mm | | | | | | | | | | |
| 6 | Fully Threaded | — | 10 | 2.8 | 3 | 120,000 | DIN 7991, ISO 10642 | 25 | 91294A541 | 8.00 |
| 8 | Fully Threaded | — | 10 | 2.8 | 3 | 120,000 | DIN 7991, ISO 10642 | 100 | 91294A207 | 8.96 |
| 10 | Fully Threaded | — | 10 | 2.8 | 3 | 120,000 | DIN 7991, ISO 10642 | 100 | 91294A208 | 10.35 |
| 12 | Fully Threaded | — | 10 | 2.8 | 3 | 120,000 | DIN 7991, ISO 10642 | 100 | 91294A210 | 10.35 |
| 14 | Fully Threaded | — | 10 | 2.8 | 3 | 120,000 | DIN 7991, ISO 10642 | 100 | 91294A211 | 10.36 |
| 16 | Fully Threaded | — | 10 | 2.8 | 3 | 120,000 | DIN 7991, ISO 10642 | 100 | 91294A212 | 10.56 |
| 18 | Fully Threaded | — | 10 | 2.8 | 3 | 120,000 | DIN 7991, ISO 10642 | 100 | 91294A213 | 15.00 |
| 20 | Fully Threaded | — | 10 | 2.8 | 3 | 120,000 | DIN 7991, ISO 10642 | 100 | 91294A214 | 11.93 |

Black-Oxide Alloy Steel Hex Drive Flat Head Screw, 90 Degree Countersink, M5 x 0.80 mm Thread, 20 mm Long

☐ Packs of 100

ADD TO ORDER

Delivers Tuesday



1pcs HK1612 Needle Roller Bearings - [16mm Bore Dia x 22mm Outside Dia x 12mm Width] Drawn Cup for Agricultural Construction Equipment Use, GCr61

Visit the Kozelo Store
4.5★★★★☆ 20 ratings | Search this page

\$4⁹⁹

FREE Returns

Size:

16mm x 22mm x 12mm

Number of Items: 1

1 2 5 10




\$15⁹⁹

For hand drilling, use a metric or ANSI drill guide based on your bit set. Clamp it over the drilling spot for alignment and stability.



Stock photo for illustration purposes

Motor Assembly Instructions



Undo the steps for
installing the J3 motor

>>

Remove J3 arm top and
bottom cover

>>


Unscrew and remove
motor mount

>>


Remove the belt

>>


Save the screws as they
will be reused in future
steps



Using wire cutters, cut the encoder and motor wires 70 mm away from the motor




Remove the J3 pulley off
the motor shaft



There are many ways to expand the shaft diameter using a drill, drill press, end mill, and lathe. This example shows a lathe.

Enlarge the hole starting with a smaller drill bit working up to a larger bit. This allows for more precise alignment and centering of the hole.



Each subsequent drill bit then follows the path of the previous one, ensuring that the hole remains true to the desired location and orientation



Continue this process up to a 14mm drill bit.

If you don't have a 14mm drill bit, you may use a boring bar once the shaft hole is large enough for it to fit inside. Manually expand the hole to 14.1mm

Tolerance is +0.05mm, -0.0mm



Using the 3D printed key, trace an outline onto the 6mm thick aluminum sheet

>>

Use a center punch to mark the location where the screw will be inserted

>>

Drill and tap the marked spot for the M4 set screw

>>

Cut the aluminum into a rough rectangular shape using a saw

>>

Refine the edges of the aluminum piece using a sander to match the outline of the key




Insert the set screw into the key and pulley to verify that the key is held by the screw in the pulley




Using a scribe, razor, etc., mark lines on the pulley to guide cutting into the pulley



Mill into J3 Pully using a $\leq 5\text{mm}$ mill bit
 $+Z\ 3.25\text{mm}$ (Going towards the screw hole)
 $-Y\ 21.8\text{mm}$
 $+X\ 2.5\text{mm}, -X\ -2.5$ (Slot needs to be 5mm wide)



*This photo shows an edge finder bit, not a mill bit



Debur the key and pully

Ensure the key's screw hole aligns with the pulley screw hole.

The m4 set screw should screw through the pully into the key.

Insert the set screw into the pulley

>>

Insert the key into the key slot

>>


Slide the J3 pulley over the motor shaft


>>

Tighten the set screw

>>

The motor and pulley are complete





Solder and heat shrink the connection from the J3 encoder to the Cat6 cable as follows:

Encoder red wire to the cable brown wire.

Encoder black wire to the cable white – brown stripe wire.

Encoder brown wire to the cable white – blue stripe wire.

Encoder blue wire to the cable blue wire



Solder the connection between the J3 motor and the motor wires, and then apply heat shrink tubing for insulation

Be sure to match colors so that red goes to red and so on.



These settings are used for the J3 Motor Driver:

J3 – (DM542T):

SW1 = OFF

SW2 = OFF

SW3 = ON


SW4 = ON

SW5 = OFF


SW6 = ON

SW7 = ON

SW8 = ON




Using an M5 tap, tap the holes that guide into the shaft in the J3 Front Spacer



Remove the motor's default screws, then disassemble the motor and gearbox

Be careful to avoid removing the inner gears from the gearbox, as was mistakenly done in the example




Holding the gears in the gearbox, slide the outer motor bracket on the gearbox shaft

>>

Insert the Side Motor Brackets

If the gears fall out of the gearbox:




The gearbox can be put back together by inserting the gears into their proper place within the gear box to the best of your ability

>>

Insert the motor shaft and power the motor, it will spin the gears into place



Screw in the gearbox
closure



Insert the inner
motor bracket

Ensure the holes on
the side of the outer
bracket align with the
holes on the side of
the inner bracket




Screw the four M5x20 hex flat head screws into the Motor Bracket, J3 Side Spacers, and J3 Front Spacer




Position the J3 belt over the pulleys and insert the motor into its designated J3 slot

Apply force towards the base until the belt experiences tension




Screw in four M4
x 90 mm socket
head screws into
motor and
bracket



Maintain tension on the J3 belt by pressing the motor downward, carefully turn each M4 x 90mm screw until it lightly engraves the aluminum arm. Ensure the engraving is clear enough to serve as a visual guide for a center punch

Do this for all four screws




Once you have the engravings, you may use the Tool for Alignment to help steady the center punch

The tool will likely break, print two



Drill the four holes using
a 3.50 mm bit

You may use any bit in
the range of 3.3 mm - 3.5
mm




Use an M4 tap to create threads in the drilled holes



On each side of the arm, drill two holes using 3.50 mm bit or any bit in the range of 3.3 mm - 3.5 mm

Use an M4 tap to create threads in the drilled holes




Assemble the gearbox and motor using the M4x90 socket head screws

Do not screw past the motor bracket



Secure the motor to the arm by fully tightening the screws into their designated positions

Do not slide the belt on the motor yet



Use the original screws from the previous J3 mount to secure the motor to the side of the arm



Attach the belt on both pulleys

If you encounter difficulty sliding the belt onto the motor: power the motor, allowing it to rotate and catch the belt, pulling it onto the pulley



Tighten the screws securely to the top and bottom cover of your robot